



## Memorandum

Subject	Updated CEMP AND CLMP
Date	3 August 2018
From	Mt Messenger Bypass Project Team
То	Hearing Commissioner

This document explains the minor changes made to the CEMP and CLMP, and reflected in the versions dated 3 August 2018 (handed up to the Commissioner at today's hearing).

## **Update to the CEMP**

Updated	Reason for Change	Change
Section		
5.6	Commissioner's	Following text has been added: It is assumed
	request for further	that the property located at 3072 Mokau Rd will
	clarification to be	be vacant during construction, However, if it is
	added to CEMP during	occupied the methods outlined above will be
	Wendy Turvey delivery	implemented to ensure that any adverse dust
	of evidence on 2	effects are managed appropriately.
	August 2018	
5.7	Commissioner's	Following text has been added: It is assumed
	request for further	that the property located at 3072 Mokau Rd will
	clarification to be	be vacant during construction, However, if it is
	added to CEMP during	occupied the methods outlined above will be
	Damian Ellerton	implemented to ensure that any adverse noise
	delivery of evidence on	effects are managed appropriately.
	2 August 2018	

## **Update to the CLMP**

Updated	Reason for	Change
Section	Change	
5	NPDC Section 42 report (30 July 2018) number 14. Request for staged report.	Following text has been added: The DSI (dated July 2018) found that the soils in areas sampled do not contain contaminants at a level that would present a risk to human health or the environment during or at the completion of works. However should unexpected
		contamination be encountered, reporting will be required as outlined in Section 4.7.3 of the CLMP. It is anticipated that this would be reported in stages.